



**KEY NOTES:**

1. Picnic shelter
2. Streambank restoration
3. Mown grama grass
4. Interpretive Signage
5. Unmown short grama grass
6. Butterfly meadow
7. Fountain sculpture
8. New pedestrian bridge
9. Mounding
10. Existing bench
11. Repair/replace existing block wall & mural
12. Trailhead signage
13. Stream access point
14. Seatwall

**LEGEND**

- Existing tree (to be removed)
- Existing shade tree
- Proposed shade tree
- Grama Grass Lawn
- Streambank Restoration
- Stone Dust
- Butterfly Meadow
- Butterfly Host Shrubs
- Existing Bench (Relocated)
- Rocks
- Trailhead Signage

500 EAST

